

### NYS Department of Environmental Conservation

## Just the other nigh

PROCOP

NYS Department of Environmental Conservation

April-7-2014

MEG

35

## close call in Glens Falls but...

PROCOP

NYS Department of Environmental Conservation

April-7-2014

MEG

# NO Spill !

NYS Department of Environmental Conservation

## **Report Oil and Hazardous Material Spills**

### Call Toll Free DEC HOTLINE 1- (800) 457-7362

Outside New York State 1- (518) 457-7362

**New York State Department of Environmental Conservation** 





#### NYSDEC SPILL REPORT FORM



Main Tanker in leaking.



NYS Department of Environmental Conservation



#### NYSDEC SPILL REPORT FORM



DEC REGION SPILL NAME:		OK ROUNDABOUT		UMBER: NAD:		6204 PICKET	
CALLER NAM CLR'S AGENC CALLER'S PH	Y: COL CO		 NOTIFIE	R'S NAME: R'S AGENCY: R'S PHONE:	COL		
SPILL DATE: CALL RECEIN		09/12/2013 09/12/2013	 D TIME:	11:45 am 12:09 pm		DISPATCHER: PJPUGSLE	_
PLACE: STREET: CONTACT:	2967 RT 9	K ROUNDABOUT F K ROUNDABOUT 2 MACORTA)	TOWN COMN	TY: I/CITY: IUNITY: ACT PHONE:	VALA	rhook	
CONT. FACTO FACILITY TY		c A ccident Truck		REPORTED E RBODY :	8 <b>Y:</b> 0 th	er	

#### CALLER REMARKS:

request response of vacuum - 8000 leaking



NYS Department of Environmental Conservation

ONE WAY

YIELD

M

NYS Department of Environmental Conservation

From: Dennis Farrar

To: Significant Incident

CC: Goertz, Keith

Subject: Spill: 1306204 SC: Kinderhook spill - Mat: #2 Fuel Oil - 8000.00 Columbia

Region 4 Spill Engineer Keith Goertz' update is below:

#### >>> Keith Goertz 9/12/2013 2:51 PM >>>

To date, 5,000 gallons of fuel oil has been recovered from bermed areas constructed near the truck. Lightning storms have now arrived in the area, and some of the cleanup activities have been suspended until that weather blows through. Businesses in the Hannaford Plaza located close to the accident site was evacuated due to significant odors/vapors and road closures..

#### >>> Keith Goertz 9/12/2013 1:18 PM >>>

The tanker appears to have a busted seam and before long, will lose its entire 8000 gallon load, to the environment. The storm drains lead to a storm water retention pond. Oil is starting to show up in the pond. Booms will be deployed in the pond and vac trucks will be used to recover the oil. There is a heavy storm forecasted in the area that could complicate cleanup efforts.

#### >>> Keith Goertz 9/12/2013 12:36:44 PM >>>

Dave Pickett is on the scene and Matt Franklin should be there shortly. The tanker truck in question is owned by Long Oil and contains #2 fuel oil. The tanker has been compromised and is leaking all over the place. Several storm drains have been impacted. Long Oil has hired Albany Tank Cleaning Services and we have hired Clean Harbors. I am not sure about Albany Tank, but Clean Harbors has a vacuum truck en route. Although the tanker is obviously leaking, the size of the hole or gash in the tanker can not be visually located at this time. So at present, the leak can not be stopped. Law enforcement knows about this as well and Lt. Hayes is responding. Thats all I have for now.

Thanks KG From: Dennis Farrar

To: Significant Incident

CC: Goertz, Keith

Subject: Spill: 1306204 SC: Kinderhook spill - Mat: #2 Fuel Oil - 8000.00 Columbia

Region 4 Spill Engineer Keith Goertz' update is below:

#### >>> Keith Goertz 9/12/2013 2:51 PM >>>

To date, 5,000 gallons of fuel oil has been recovered from bermed areas constructed near the truck. Lightning storms have now arrived in the area, and some of the cleanup activities have been suspended until that weather blows through. Businesses in the Hannaford Plaza located close to the accident site was evacuated due to significant odors/vapors and road closures..

#### >>> Keith Goertz 9/12/2013 1:18 PM >>>

The tanker appears to have a busted seam and before long, will lose its entire 8000 gallon load, to the environment. The storm drains lead to a storm water retention pond. Oil is starting to show up in the pond. Booms will be deployed in the pond and vac trucks will be used to recover the oil. There is a heavy storm forecasted in the area that could complicate cleanup efforts.

#### >>> Keith Goertz 9/12/2013 12:36:44 PM >>>

Dave Pickett is on the scene and Matt Franklin should be there shortly. The tanker truck in question is owned by Long Oil and contains #2 fuel oil. The tanker has been compromised and is leaking all over the place. Several storm drains have been impacted. Long Oil has hired Albany Tank Cleaning Services and we have hired Clean Harbors. I am not sure about Albany Tank, but Clean Harbors has a vacuum truck en route. Although the tanker is obviously leaking, the size of the hole or gash in the tanker can not be visually located at this time. So at present, the leak can not be stopped. Law enforcement knows about this as well and Lt. Hayes is responding. Thats all I have for now.

Thanks KG



#### NYSDEC SPILL REPORT FORM



#### CALLER REMARKS:

FACILITY TYPE :

Vessel

Vessel sank and caller is reporting the potential of a spill. No visual fluids loss. 5000 gals of fuel on vessel. NRC 1071266

WATERBODY:

ATLANTIC OCEAN



#### NYSDEC SPILL REPORT FORM



#### CALLER REMARKS:

Vessel sank and caller is reporting the potential of a spill. No visual fluids loss. 5000 gals of fuel on vessel. NRC 1071266



PLACE:

STREET:

#### NYSDEC SPILL REPORTFORM



CALLER REMARKS:

Vessel sank and caller is reporting the potential of a spill. No visual fluids loss. 5000 gals of fuel on vessel. NRC 1071266

## Heard this one before!

### Photo Album

by kjgomez 1/16/14 Overflight by USCG

#### and the second second

and the second se

### 01.16.2014 10:03



All solutions and all solution

01.16.2014 10:01







#### Tug Pushy - NRC # 1071294 Tug Sea Lion - NRC #1071266 Off Atlantic Beach/Rockaway Inlet Long Island/Queens



DRAFT

Commissioner





DRAFT

#### Tug Aground NRC #1071294 Atlantic Beach, Nassau Co. Long Island South Shore









#### NYSDEC SPILL REPORTFORM



DEC REGION	: 2	SPILL NUMBER:	1306225
SPILL NAME:	MARINERS HARBOR	DEC LEAD:	RMPIPER
CALLER NAM	E: SAMUEL WOOD	NOTIFIER'S NAM	E: SAMUEL WOOD
CLR'S AGENO	CLEAN WATER OF NY	NOTIFIER'S AGE	NCY: CLEAN WATER OF NY
CALLER'S PH	ONE:7189814600 12	NOTIFIER'S PHO	NE: _7189814600 12
SPILL DATE:	09/12/2013	SPILL TIME: 8:10 p	m DISPATCHER:
CALL RECEI	VED DATE: 09/12/2013	RECEIVED TIME: 9:12 p	m jwmaher
		SPILL LOCATION	
PLACE:	MARINERS HARBOR	COUNTY:	Richmond
CTOFFT.			
STREET:	3249 RICHMOND TERRACE	TOWN/CITY:	New York City
STREET:	3249 RICHMOND TERRACE SOUTHAVE/RICHMOND TER	TOWN/CITY: COMMUNITY:	New York City STATEN ISLAND
CONTACT:			STATEN ISLAND
	SOUTHAVE/RICHMOND TER SAMUEL WOOD	COMMUNITY:	STATEN ISLAND ONE: 7189814600 12
CONTACT:	SOUTHAVE/RICHMOND TER SAMUEL WOOD OR: Equipment Failure	COMMUNITY: CONTACT PHO	STATEN ISLAND   ONE: 7189814600 12   TED BY: Other 12

#### CALLER REMARKS:

Transferring oil between tanks on barge. Oil ended up coming out of the top of a valve on the tank. Valve may have possibly gotten stuck. Rough estimate was 1,000 barrels. Oil was spread out due to the rain.



Randy Austin's update on the Clean Waters spill is below:

Ryan Piper did a brief shoreline survey this morning, to the east and west of the facility, and only saw small sheens. The booming continues at the facility, to button up whatever oil is around the vessel. Ryan is on a contractor's boat with the USCG and the south shoreline of Shooters Island is clean. They spotted a 2" X 25" slick patch of partially emulsified oil down by the Akzo salt facility, but not much other than sheens. The will now turn back west and survey the north shore of Shooters and the confluence of Newark Bay Arthur Kill and the KVK. I spoke with Gary Pearson of NJDEP and they are reporting sheens up along the Bayonne shoreline of the Kill Van Kull and Newark Bay, and they are dispatching responders to check that location. Ryan will report back when he gets more information about Shooters Island.

While the report says 1,000 barrels (= 42,000 gals), the reports from the scene (Piper, contractors) says it looks more like 6000-8000 gals. We'll get a better picture of the quantity when we have completed the survey.

We will be pursuing enforcement and we'll let the Natural Resources folks decide on whether or not a NRDA is warranted.

Randy Austin's update on the Clean Waters spill is below:

Ryan Piper did a brief shoreline survey this morning, to the east and west of the facility, and only saw small sheens. The booming continues at the facility, to button up whatever oil is around the vessel. Ryan is on a contractor's boat with the USCG and the south shoreline of Shooters Island is clean. They spotted a 2" X 25" slick patch of partially emulsified oil down by the Akzo salt facility, but not much other than sheens. The will now turn back west and survey the north shore of Shooters and the confluence of Newark Bay Arthur Kill and the KVK. I spoke with Gary Pearson of NJDEP and they are reporting sheens up along the Bayonne shoreline of the Kill Van Kull and Newark Bay, and they are dispatching responders to check that location. Ryan will report back when he gets more information about Shooters Island.

While the report says 1,000 barrels (= 42,000 gals), the reports from the scene (Piper, contractors) says it looks more like 6000-8000 gals. We'll get a better picture of the quantity when we have completed the survey.

We will be pursuing enforcement and we'll let the Natural Resources folks decide on whether or not a NRDA is warranted.

### ENVIRONMENTAL SENSITIVITY INDEX MAP











#### NYSDEC SPILL REPORT FORM

DEC REGION: SPILL NAME:	1 LONG ISLA	ND SOUND 2.5 MIL	ES FROM NO	SPILL NU BABEILLEM		1309694 NJACAMPO
CALLER NAME CLR'S AGENCY CALLER'S PHO	NY POW	ERAUTHORITY		NOTIFIE		JOHN KA HABKA NY POWER AUTHORITY (914) 681-6308
SPILL DATE: CALL RECEIVI	ED DATE:	01/06/2014 01/06/2014	SPILL TIN RECEIVE	D TIME:	3:15 pm 4:44 pm	DISPATCHER: JDW HEATL
	LONG ISLAN NORTH HEMF JOHN KAHAI	D SOUND 2.5 MILE PSTEAD		TH CIONA TOWN COMN	\$ŸÆAD /CITY: IUNITY: ACT PHONE:	Nassau North Hempstead NORTH HEMPSTEAD (914) 681-6308
CONT. FACTOR FACILITY TYP	· · · ·	oment Failure utional, Educational,	Gov., Other		REPORTED E RBODY :	<b>Y:</b> Responsible Party LONG ISLAND SOUND

#### CALLER REMARKS:

Clean-up not started at this time. Fault in an electical cable.

#### SIGNIFICANT SPILL NOTIFICATION

At 19:58 hours on January 12 2014, Billy Stuber of PSEG/LIPA reported a leak in the "feeder line for 138 Cable 292 from the 2K Valley Stream substation to the 2WB Barrett Substation" located on Daly Blvd. in Oceanside (Spill 1309916). The cable meter gave the loss as approximately 500 gallons. PSEG/LIPA began investigating to determine the exact location of the cable leak.

At 07:50 hours on January 13 2014, a citizen reported a sheen in the Mill River near the Long Island Railroad platform in Oceanside, which is immediately north of Island Park (Spill 1309919). Willie Gabin of DEC Spills and the US Coast Guard responded. At 1200, January 13, 2014 the Nassau County PD reported that they had been notified a sheen in the Mill River and had performed an overflight to assess the situation.

As of 13:00 hours today, DEC and the Coast Guard are on site with Marty Bruscella of PSEG/LIPA, H2M Group (PSEG/LIPA's consultant), and Waste Recycling Services, (PSEG/LIPA's cleanup contractor). The leak rate has been reduced to 30gph, and the amount spilled is currently estimated to be approximately 700-800gal. Some of this product is recoverable, and recovery efforts are underway.

This office will keep you updated on new developments.

\*\*\*THIS IS NOT RELATED TO SPILL 1309694 (THE LEAK IN THE CROSS-LONG ISLAND SOUND CABLE IN GLEN COVE\*\*\*







- 0







US DOC | NOAA | NOS | NOAA Office of Response & Restoration Email Comments: orr.erma@noaa.gov ©

Coastal Response Research Center © 2007-2014 University of New Hampshire

H

MA Environmental Response Management Application Atlantic





NYPA Cable Oil Leak DEC Spill #1309694 - NRC #1070239 Long Island Sound







#### NYSDEC SPILL REPORTFORM



DEC REGION:	1	SPILL NUMBER:	1309694
SPILL NAME:	LONG ISLAND SOUND 2.5 MILES FROM NO	OBECHLEADSTEAD	NJACAMPO

1858 Hrs: RJP took call from P.O. Mello- Sensor fault in cable approx. 0700 Hrs on 1/6/14, release of approx. 400 gal of low viscosity cable oil. They have throttled down the cable, to a current leak rate of 1-5 gal/hour. They have contacted Miller Marine- they will not be responding tonight and are not sure if they will be able to respond tomorrow due to water conditions. They are still attempting to find the exact location of the leak, but have determined it to be about 2.5 miles north of the Hempstead Harbor Station. Contact at NY Power Authority is Robert Schleg- Office(914) 287-3794 Cell (914) 774-1878. RJP.

1918 Hrs: RJP made call to Robert Schleg. States fault in their "C" phase cable running from Hempstead Harbor to New Rochelle. They have determined the location of leak to 2.87 miles north from the Hempstead Harbor South Station. The cable is burried 5' - 10' below the bed. They will have divers attempt to find the leak using electrical methods, will excavate the cable and perform the repair. This process may take several weeks. They are unable to shut down the cable, as salt water intrusion would cause \$Millions in damage. They have not put eyes on the surface spill and are not sure when they will be able to do so. They have not gotten any reports of contamination on shore. RJP.

1940 Hrs: Email to NA and KG informing of current situation. No actionable information, will keep updated. RJP.

CABLE UNCOVERED AND CAPPED, LEAK STOPPED, FINAL REPAIRS, RE-SPLICE TO CABLE TO BE COMPLETED WHEN ABLE, NO LONGER THREAT, 175-200 CUBIC YARDS OF SOLIDS, 1287 GALLONS OILY WATER RECOVERED,

PIN		<u>T &amp; A</u>		COST CENTER	
CLASS:	B3	CLOSE DATE:	03/10/2014	MEETS STANDARDS:	False



#### NYSDEC SPILL REPORT FORM



DEC REGION:	1	SPILL NUMBER:	1309694
SPILL NAME:	LONG ISLAND SOUND 2.5 MILES FROM NO	OBECHLEADSTEAD	NJACAMPO

1858 Hrs: RJP took call from P.O. Mello- Sensor fault in cable approx. 0700 Hrs on 1/6/14, release of approx. 400 gal of low viscosity cable oil. They have throttled down the cable, to a current leak rate of 1-5 gal/hour. They have contacted Miller Marine- they will not be responding tonight and are not sure if they will be able to respond tomorrow due to water conditions. They are still attempting to find the exact location of the leak, but have determined it to be about 2.5 miles north of the Hempstead Harbor Station. Contact at NY Power Authority is Robert Schleg- Office(914) 287-3794 Cell (914) 774-1878. RJP.

1918 Hrs: RJP made call to Robert Schleg. States fault in their "C" phase cable running from Hempstead Harbor to New Rochelle. They have determined the location of leak to 2.87 miles north from the Hempstead Harbor South Station. The cable is burried 5' - 10' below the bed. They will have divers attempt to find the leak using electrical methods, will excavate the cable and perform the repair. This process may take several weeks. They are unable to shut down the cable, as salt water intrusion would cause \$Millions in damage. They have not put eyes on the surface spill and are not sure when they will be able to do so. They have not gotten any reports of contamination on shore. RJP.

1940 Hrs: Email to NA and KG informing of current situation. No actionable information, will keep updated. RJP.

CABLE UNCOVERED AND CAPPED, LEAK STOPPED	FINAL REPAIRS, RE-SPLICE TO CABLE TO BE COMPLETED
WHEN ABLE, NO LONGER THREAT, 175-200 CUBIC Y/	ARDS OF SOLIDS, 1287 GALLONS OILY WATER RECOVERED,

<u>PIN</u>	<u>T &amp; A</u>	COST CENTER	
CLASS: B3	CLOSE DATE: (	03/10/2014 MEETS STANDARDS:	False

